


Daikin FTXC50B/RXC50B



?????????: ??? ????????????? ?????

??????? : Daikin FTXC50B/RXC50B

867 €


????? ??? ??????? ??? ?? ???????

????????????Daikin

????????

???????????? Daikin FTXC50B/RXC50B SENSIRA R-32

- [illegible]



????????????

❄️ ???? - BTU: 17.333

❄️ ???? - ?????????? ?????: A++

SEER: 6.45

?????????? ?????. M?????(mm): 785/288/250
 ?????? ??????? ?????.????????: 57 dB

☀️ ???????? - BTU: 13.307

❄️ ???????? - ?????????? ??????: A+

❖ SCOP: 4.42

?????????? ?????. M?????(mm): 658/550/273
 ?????? ??????? ?????.?????????: 65 dB

?????? ????????

??? ?????? ????????????? ??? ?? ?????? ??????.